

Rimforsa, Sweden, 1998

Pedestrian & bicycle road at viaduct under high way. Steep, silt-sandy slopes with ground water pouring out resulting in great risk for erosion. Slopes covered with THULICA KK-8, coir ECB, seeded and planted.

